CAMPUS OBSERVATIONS

Classrooms

- •Classrooms have adequate space, and each room opens to common area
- Minimal daylighting in classrooms
- •Sufficient number of permanent classrooms, particularly after restructuring classes into departments
- •Classrooms have doors to access outside
- Music classroom too small to support number of students enrolled in class •Special Education classrooms appear to

be integrated throughout the campus

- Library/ Media
- •Adjacent to MPR and one classroom wing; not as convenient for other classroom wings and buildings
- ·Somewhat small, with no access to daylighting

•Have adequate number of computers to support one class; lack books due to funds

Food Service

- •Is adequately-sized and functions well for
- •Students queue outside with no shade or rain protection
- •Food service has two (2) double-wide entries/ exits; exit feeds into central courtyard
- •Removing planter bed near exit would improve flow of students into courtyard

Multi-Purpose Room

- Has resilient flooring rather than carpet Described as functioning well for current needs; could use microphones for stage during performances
- •Cannot expand MPR space to another indoor/outdoor area when needed

•Stage cannot be used as separate classroom (no moveable partition, just curtains)

Admin & Support Spaces

- •Main office is located toward front of school, but not at the end of the main pedestrian pathway (MPR resides there); does not stand out visually for visitors/newcomers
- support prep work
- Staff lounge lacks space and flexibility •Each wing has a teacher workroom to

CAMPUS OVERVIEW

Rancho San Joaquin Middle School is a 7-8 seasonal school, situated in a residential setting. The school is directly adjacent to and south of the I-405, between Culver Drive and University Drive.

The main Administrative office is located at the front of the campus adjacent to the parking lot, along the main pathway that leads directly to the Multipurpose Room (MPR). Adjacent to the MPR is the Library, which is a somewhat small but inviting space. Also located on the Rancho campus is the District's Nutrition Services Department and Central Kitchen.

The three academic wings in the main building are each organized in pod configurations surrounding a central breakout/resource area with computers for student use. There are two additional classroom buildings, one at the front of the school and one near the hardcourts toward the back of the campus. There are also two portables used as

Rancho San Joaquin is a California Distinguished School as well as a National Blue Ribbon School. In conjunction with its strong academic program, the school implements its *Rancho R.U.L.E.S.* positive behavior program, which encourages and rewards students who act with the following ideals in mind: Respect, Unwavering Integrity, Leadership, Effort, and **S**ocial Responsibility

Mission Statement: to enable all students to become contributing members of society empowered with the skills, knowledge, and values necessary to meet the challenges of a changing world, by providing the highest quality educational experience the school and its stakeholders can envision.

SCHOOL





General Condition

- •General need for update of school, exterior façade and interior elements; some casework in need of replacement/
- Need for more daylighting/ natural lighting opportunities throughout the building

Building Systems

- •HVAC is provided by multizone roof top units that were installed during 1999 modernization
- Ductwork is fiberboard and is leaky •Site also has a kitchen and walk-in freezers that serve much of the district •HVAC is controlled by a Carrier EMS
- Site has photovoltaic panels

Technology

- •Library has computers to accommodate full class; computer areas exist outside classrooms in central pod; some classrooms have computers
- •Computers require updating and/or replacement

Specialty Labs

•Read 180 Lab; Common Area computer labs, project based lab (formally wood shop)

Outdoor Areas

- •Trees near playfields are very large and provide nice shade opportunities; aside from these trees, not many shade opportunities near hardcourts and playfields
- •Central courtyard has lunch shade



structures and some trees near seatwalls for shade

Vehicular Access/ Parking/ Drop-Off


•Parking and drop-off described as adequate

Rancho San Joaquin Middle School



4861 Michelson Drive | Irvine, CA 926 **Site Analysis**

LPA







SCHOOL STATISTICS

Grades:	7-8
Building SF:	67,884
Portable SF:	4,800
2010/11 Enrollment:	840
Year Built:	1972
Modernization:	2001
Site Acreage:	20.0
# Portables:	5

CLASSROOM COUNT

General Classroom (2 Portables)	17
Science	7
Art / Tech	2
Music*	1
Special Education	4
Physical Education	2
Computer Lab/Classroom	1
Open/Unused	2
TOTAL	36
*Also may use MPR for music	

Wayfinding/ Entry/ Welcome	0	•	0	0	
Natural Daylighting	•	0	0	0	
Controllability (Daylight, Lighting, HVAC)	0	•	0	0	
Flexibility in Classrooms	0	•	0	0	
Access to Technology	0	•	0	0	
Collaboration	0	•	0	0	
Student Display	0	•	0	0	
MPR	0	•	0	0	
Library/ Media	0	•	0	0	
Functional Landscaping	0	•	0	0	
Energy Consumption	0	•	0	0	
General Condition	0	•	0	0	

Comp. Computer Lab/Area

Open Unused Classroom

10.20.11









Front of School

Front Entrance to Quad

Entry to Administration and MPR

Parking and Drop-Off









Entry to Portables and Hardcourts

Main Office Entrance

View of Outer Components of Central Kitchen

Nutrition Portable and Storage









Basketball Courts

Hardcourts

Playfields



Joaquin Middle School





Service Windows

Staff Lounge





Sheltered Lunch Area Outdoor Stage in Courtyard









Courtyard Bike Racks Main Office Waiting Area









Staff Workroom Principal's Of



Site Analysis – Rancho 4861 Michelson Drive | Irvine,









Health Office Psychologist Office




Counselor's Office



28





MPR Stage

MPR Backstage

Library

Book Storage









Food Service

Additional Food Serving Area

Central Kitchen













Central Kitchen Interior Freezers

Central Kitchen Exterior Freezers

Central Kitchen Office

Central Collaboration Space










Pod Workroom

Pod Conference Room

Computer Lab

Science Classroom









Art Classroom

Music Classroom

Video Production

Site Analysis – Rancho San Joaquin Middle School 4861 Michelson Drive | Irvine, CA 92612









Woodshop Typical Portable Nutrition Services Portable Instrument Rental Portable









Boy's Locker Room Cardio Workout Room Typical Bathroom

